



U.S. Department  
of Transportation

## United States Coast Guard



# LOCAL NOTICE TO MARINERS JANUARY WEEKLY EDITION

NOTICE NUMBER 01A-98

January 06, 1998

Electronic Bulletin Board Service: (703) 313-5910  
300 to 28.8k bps, 8 data bits, no parity, 1 stop bit  
NIS watchstander, 24 hours a day at (703) 313-5900  
Boating Safety Classes or Information: 1-800-869-SAIL (7245)

**\*\* INTERNET ADDRESS \*\***  
<http://www.navcen.uscg.mil>  
OR  
<gopher://gopher.navcen.uscg.mil>

**\*\* FOURTEENTH DISTRICT HOMEPAGE \*\***  
<http://www.pixi.net/~d14pao/>

Issued by: Commander, Fourteenth Coast Guard District (oan)  
PJJK Federal Building, Room 9-236  
300 Ala Moana Boulevard, Honolulu, HI 96850-4982  
Telephone: (808) 541-2315 Nights: (808) 541-2500 Fax: (808) 541-2309  
Email: [mwhaley@d14.uscg.mil](mailto:mwhaley@d14.uscg.mil)

Navigation information having been of immediate concern to the Mariner, and promulgated by the following broadcasts, has been incorporated in this notice when still significant:

⇒ CCGD14 (D14) BNMs: 476-97 to 003-98.  
⇒ COGARD MARIANAS SECTION (MARSEC) BNMs: 078-97 to 150-98.

NOTES:

- (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.
- (2) The Local Notice to Mariners is published in its entirety once a month. The Monthly Edition should be retained as a reference for subsequently issued Weekly Supplements. The Weekly Supplements will be published in intervening weeks and will contain only new information with the exception of DISCREPANCIES-DISCREPANCIES CORRECTED section which is an accurate list maintained each week.

REFERENCES: Light List, Vol. VI, Pacific Coast and Pacific Islands, 1997 Edition (COMDTPUB P16502.6).  
U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii (31st Edition).

**REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT**

## I. SPECIAL NOTICES

### **HAWAIIAN ISLANDS DGPS STATUS AS OF 06 JAN 98:**

The Differential GPS broadcast site at Upolu Point will be off-air from 0001Z 02 MAR 98 to 2359Z 06 MAR 98. The Differential GPS broadcast site at Kokole Point will be off-air from 0001Z 09 MAR 98 to 2359Z 12 MAR 98. The status of the Differential GPS broadcast sites at Kokole Point and Upolu Point may be obtained by contacting the NAVCEN WEST watchstander at (707) 765-7612.

### **ERROR IN WEST COAST TIDE TABLE FOR 1998:**

Daily predictions for Port Chicago, California, found on pages 176 through 179 in the NOS **Tide Tables 1998 West Coast of North and South America Including the Hawaiian Islands** are in error. The 1998 tide predictions published for Port Chicago should NOT be used for any purpose whatsoever. In the interest of marine safety and navigation, corrected copies of the 1998 predictions for Port Chicago, California, may be obtained by contacting the publisher of the table or by accessing the Oceanographic Products and Services Division's Web Page at <http://www.opsd.nos.noaa.gov>.

### **IMPROVED LOCAL NOTICE TO MARINERS AVAILABILITY:**

In an effort to provide more timely navigation information, as well as reduce printing and mailing costs, the 14th Coast Guard District Local Notice to Mariners (LNM) is now available via facsimile, or through Internet access. To receive the LNM via fax, please call (808)541-2317 or e-mail at [mwhaley@D14.uscg.mil](mailto:mwhaley@D14.uscg.mil). If you prefer the Internet alternative, the LNM can be obtained by visiting [www.navcen.uscg.mil](http://www.navcen.uscg.mil). Either of these mediums will make the information contained in the LNM available 3 to 7 days earlier than regular mail. If you wish to use one of these options, please notify us and we will take you off the regular mailing list.

## II. DISCREPANCIES - DISCREPANCIES CORRECTED

### **Abbreviations normally used in the Local Notice to Mariners**

BNM - Broadcast Notice to Mariners	TRUB - Temporarily Replaced by Lighted Buoy
LNM - Local Notice to Mariners	TRUB - Temporarily Replaced by Unlighted Buoy
TUB - Temporary Unlighted Buoy	TLB - Temporary Lighted Buoy
TLT - Temporary Light	TDBN - Temporary Daybeacon
IMPCHA - Improper Characteristics	INOP - Inoperative
REDINT - Reduced Intensity	

**Shaded text denotes new discrepancy since last LNM.**

### **DISCREPANCIES:**

LLNR	Name of Aid	Status	Charts Affected	BNM Reference	LNM Reference
28355	Kahului Harbor Breakwater Light	EXTINGUISHED	19342	001-98	01A-98
28820	Sampan Channel Daybeacon 4	TRUB	19359		13-97
28150	Napoopoo Point Light	EXTINGUISHED	19332		01-98

### **DISCREPANCIES: Private Aids:**

LLNR	Name of Aid	Status	Charts Affected	BNM Reference	LNM Reference
28005	NOAA Buoy 51004	ADRIFT	19008/19009	294-97	33-97
28573	NASA/NOAA Research Lighted Buoy	MISSING		408-97	44-97
29340	Keehi Lagoon Pipeline Marker Buoy "C"	OFF STATION	19367	466-97	50-97
29655	Barbers Point West Beach Marina Light 1	EXTINGUISHED	19360	305-97	34-97
30811.1	Agat Small Boat Harbor Daybeacon 1	IMPCHA	81048	001-96	01-96
30811.5	Agat Small Boat Harbor Daybeacon 5	IMPCHA	81048		44-96
None	Samoa FAD Buoy "A" East Bank	MISSING	83484		21-95
None	Samoa FAD Buoy "D" Tutuila Island	MISSING	83484		25-95
None	Samoa FAD Buoy "F" Anuu Island	MISSING	83026		25-95
None	Samoa FAD Buoy "H" South Bank	MISSING	83026		25-95
None	Samoa FAD Buoy "I" East Bank	MISSING	83026		25-95

**II. DISCREPANCIES - DISCREPANCIES CORRECTED** Continued.

**DISCREPANCIES: Private Aids:**

LLNR	Name of Aid	Status	Charts Affected	BNM Reference	LNM Reference
None	FAD Buoy "E"	MISSING	19320	150-97	15-97
None	FAD Buoy "G"	MISSING	19320		47-97
None	FAD Buoy "N" Cape Halawa	MISSING	19340	002-98	01A-98
None	FAD Buoy "O"	MISSING	19351		47-97
None	FAD Buoy "Q" Pauwela Point	MISSING	19340		01A-98
None	FAD Buoy "T" Makapuu Point	MISSING	19340		01A-98
None	FAD Buoy "X"	EXTINGUISHED	19430	350-97	39-97
None	FAD Buoy "Z"	MISSING	19380		18-97
None	FAD Buoy "BO" Barbers Point	EXTINGUISHED	19357		47-97
None	FAD Buoy "CK"	EXTINGUISHED	19381	254-97	27-97
None	FAD Buoy "DK"	OFF STATION	19381		05-97
None	FAD Buoy "EK" Hanalei	MISSING	19381		27-96
None	FAD Buoy "FF" Pukalua Point	MISSING	19340		01A-98
None	FAD Buoy "HO"	MISSING	19340		47-97
None	FAD Buoy "JJ"	MISSING	19340		47-97
None	FAD Buoy "LA"	OFF STATION	19347		21-97
None	FAD Buoy "LL" Hauula	MISSING	19357		01A-98
None	FAD Buoy "MC"	MISSING	19340		21-97
None	FAD Buoy "QQ" Mokuu	MISSING	19320		14-96
None	FAD Buoy "RN" Palima Point	OFF STATION	19320		01A-98
None	FAD Buoy "TT"	EXTINGUISHED	19320		47-97
None	FAD Buoy "UU"	MISSING	19320		47-97

**DISCREPANCIES CORRECTED:**

LLNR	Name of Aid	Status	Charts Affected	BNM Reference	LNM Reference
30670	Agana Small Boat Basin Approach Light Rear Range	WATCHING PROPERLY	81048		52-97
30725	Apra Outer Harbor Pier Dog Light	WATCHING PROPERLY	81054		52-97
30795	Apra Inner Harbor Approach Range Rear	WATCHING PROPERLY	81054		52-97
30800	Apra Harbor Inner Harbor Range Front	WATCHING PROPERLY	81054		52-97
30805	Apra Inner Harbor Range Rear	WATCHING PROPERLY	81054		52-97
30811	Agat Harbor Entrance Lighted Buoy "AG"	WATCHING PROPERLY	81048 and 81054		52-97
30850	Rota West Harbor Rear Range	WATCHING PROPERLY	81063		52-97

**III. NEW TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED** None.

**IV. CHART CORRECTIONS (C)**

Corrective action affecting charts is contained in this section. Chart Corrections are listed numerically by chart number beginning with the lowest and progressing through all charts affected. The correction listed pertains to that chart only. *It is up to the mariner to decide which charts are to be corrected.* The following example explains the individual elements of a typical correction.

Chart Number	Chart Edition	Edition Date	Last LNM	Datum	Source Agency	Current LNM
Corrective Action	Object of Corrective Action					Position

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. A chart number preceded by an asterisk (\*) indicates that the chart is the largest scale chart that the correction appears on. When (temp) appears below the chart number the chart correction is temporary in nature. The letter (N) preceding the current Notice to Mariners number indicates a Distribution Limited (not for sale) chart or publication. It is usually for U.S. Navy, government owned or chartered ships only. Courses and bearings are given in degrees clockwise from 000° T. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles.

AD YR	Astronomic Datum (Year)	NAD YR	North American Datum (Year)
BABSAD	BAB South Astro Datum	OHD	Old Hawaiian Datum
LD	Local Datum	TD	Togcha Datum
WGS YR	World Geodetic System (Year)		

<b>19357</b>	<b>20<sup>th</sup> Edition</b>	<b>09/21/96</b>	47/96	NAD 83	NOS CL-1643/97	01A/98
Substitute	1 ½ fm sounding for 2 ¾ fm sounding					21°19'00.5"N 158°07'34.7"W

**V. ADVANCE NOTICE OF CHANGES IN AIDS TO NAVIGATION (A)** None.

**VI. PROPOSED CHANGES IN AIDS TO NAVIGATION (P)** None.

**VII. GENERAL** (See LNM 01-98, the current Monthly Edition and subsequent supplements for a complete list of notices.) None.

**VIII. CORRECTIONS TO LIGHT LIST, VOLUME VI: PACIFIC COAST AND PACIFIC ISLANDS 1997:** None.

**IX. ADDITIONAL ENCLOSURES:**

Enclosure (1) U.S. Coast Pilot 7, Pacific Coast: California, Oregon, Washington, and Hawaii, 1997 (31st) Edition. Change No. 5.

END OF CCGD 14 LOCAL NOTICE TO MARINERS NO. 01A-98.

T. H. COLLINS  
Rear Admiral, U. S. Coast Guard  
Commander, Fourteenth Coast Guard District